


1 Board Overview



Connectors	1	3pin Header	Power Input
	2	Jumper	Power Jumper
	3	34pin Header	Transportstream Output
	4	10pin Header	I ² C-Bus for Display + Keyunit
	5	10pin Header	RS232
	6	F Connector 75 Ω	RF (Loopthrough-) Output
	7	F Connector 75 Ω	RF Input
	8	Jumper	setting LNB Power on/off for 7
	9	Jumper	setting LNB Power on/off for 8

LEDs	a	LED green	3,3 V ok
	b	LED green	5 V ok
	c	LED green	RF Lock
	d	LED green	NIM found
	e	LED green	alive
	f	LED green	RF Lock (same as c)

